

RBMP Water body information sheet for water body 100325 in Solway

General details

Water body name:	Clatteringshaws Loch
Water body Identifier code:	100325
Area:	3.87 km ²
Water body category:	Lake
Baseline:	Y
River basin district:	Solway Tweed
Area advisory group:	Solway
Catchment:	River Dee (Solway)
Associated protected areas:	
Associated groundwater:	
Responsible body:	SEPA Dumfries & Galloway
Heavily modified:	Yes
Artificial:	No
Typology:	Lowland Large Low alkalinity Deep
National Grid Reference:	NX 54237 77007
Latitude:	55.06608
Longitude:	-4.28409

Current status of this water body

We have classified this water body as having an overall status of Moderate ecological potential with Medium confidence in 2008 with overall ecological status of Bad and overall chemical status of Pass.

It is important to note that the five classification ecological potential classes for Heavily Modified Water Bodies (HMWBs) and Artificial Water Bodies (AWBs) combine the level of mitigation measures for water levels and flow and physical habitat with measurements of the biological and chemical water quality. For example, a HMWB could have all the mitigation measures in place for the use (eg hydropower) to allow it to reach good ecological potential, but if water quality is poor due to elevated phosphorus levels, its overall ecological potential assessment could be moderate, poor or bad depending on the severity of the impact.

RBMP Water body information sheet for water body 100325 in Solway

This overall classification of status is made up of many different tiers of classification data. A complete set of classification data for 2008 is shown at the end of this document.

Targets for the future status of this water body

We have set environmental objectives for this water body over future river basin planning cycles in order that sustainable improvements to its status can be made over time, or alternatively that no deterioration in status occurs, unless caused by a new activity providing significant specified benefits to society or the wider environment.

For this water body we have set the overall environmental objectives for the first, second and third River Basin Management Planning (RBMP) cycles as:

Year	2008	2015	2021	2027
Status	Moderate ecological	Potential	Good	Good

We have established an ongoing programme of monitoring in order to identify pressures on our water bodies. The pressures listed below contribute to this water body's failure to meet good ecological status. River basin planning allows us to plan improvements for particular parameters over time. We have collaborated with others to identify measures which will act to protect or improve our water environment in order that all water bodies reach good status over successive RBMP cycles.

Pressures and measures on this water body

The pressures listed below contribute to this water body's failure to meet good ecological status or potential. River basin planning allows us to plan improvements for particular parameters over time. We have collaborated with others to identify measures which will act to protect or improve our water environment in order that all water bodies reach good status over successive RBMP cycles.

The following table shows our collated information on the pressures on this water body, their causes and the measures which could be introduced to mitigate their effects. We have also indicated the current funding status of the measure; with projected measures being potentially funded and agreed measures having funding in place. Finally, we have included information on the potential or actual owner of the measure, the date it will be effective and information on the justification for extending the deadlines or for setting an alternative objective, where appropriate.

Pressure	As a Result of	Assessment Parameter	Objective	Reasons for Failure
	Measure	Funding	Owner	Effective date
Diffuse Source Pollution	Production of non-renewable electricity (eg: by coal, gas,	Acidification	Good by 2015	

RBMP Water body information sheet for
water body 100325 in Solway

Pressure	As a Result of	Assessment Parameter	Objective	Reasons for Failure
	Measure	Funding	Owner	Effective date
	nuclear or pumped hydro)			
Diffuse Source Pollution	Forestry	Phosphorus	Good by 2015	
	Non-urban land management measures	Neither Agreed nor Projected	Forestry Commission Scotland	31/12/2014
Abstraction	Production of renewable electricity (NB nuclear and pumped hydro are not renewable forms of electricity generation) Impounding - weir / dam	Change in the outflow from the lake	Good by 2015	
	Control pattern/ timing of abstraction (Hands off flow/ utilisation of storage (new/existing)	Neither Agreed nor Projected	Scottish Power	31/12/2007
Flow Regulation	Production of renewable electricity (NB nuclear and pumped hydro are not renewable forms of electricity generation) Impounding - weir / dam	Change in the outflow from the lake	Good by 2015	
	Appropriate management of rate and range of artificial drawdown	Neither Agreed nor Projected	Scottish Power	31/12/2007
Morphological Alterations	Production of renewable electricity (NB nuclear and pumped hydro are not renewable forms of electricity generation) Impounding - weir / dam	Fish passage	Good by 2015	
	Removal of barriers or provision of mechanisms to enable fish migration	Neither Agreed nor Projected	Scottish Power	31/12/2007
Morphological Alterations	Production of renewable electricity (NB nuclear and pumped hydro	Single pressure - Shore	Good by 2015	

RBMP Water body information sheet for
water body 100325 in Solway

Pressure	As a Result of	Assessment Parameter	Objective	Reasons for Failure
	Measure	Funding	Owner	Effective date
	are not renewable forms of electricity generation) Impounding - weir / dam			
	Improve Modified Habitat	Neither Agreed nor Projected	Scottish Power	31/12/2007

Future work

Additional work to identify pressures and to develop and implement measures to mitigate their impacts will continue over subsequent river basin cycles.

Complete classification for this water body in 2008


Parameter	Status	Confidence of Class
OVERALL STATUS	MODERATE ECOLOGICAL POTENTIAL	MEDIUM
Pre-HMWB status	Bad	Medium
Overall chemistry	Pass	Low
Priority substances	Pass	Low
Lead	Pass	Low
Overall ecology	Bad	Medium
Physico-Chem	Moderate	High
Dissolved Oxygen	High	Low
Total Phosphorus	Moderate	High
Salinity	High	High
Acid Neutralising Capacity	High	High
Biological elements	Poor	Low
Phytobenthos	High	Low
Macrophytes	High	Low
Benthic invertebrates	Good	High
Macro-invertebrates (acid)	Good	High
Macro-invertebrates (CPET)	High	Low
Alien species	High	Low

RBMP Water body information sheet for water body 100325 in Solway

Parameter	Status	Confidence of Class
Fish barrier	Poor	Low
Phytoplankton	High	High
Chlorophyll a	High	High
Cyanobacteria	High	Low
Specific pollutants	Pass	High
Ammonium	Pass	High
Hydromorphology	Bad	Medium
Morphology	Poor	Medium
Hydrology	Bad	Medium
Water quality	Moderate	
Morphological pressures	Poor	

Location of this water body

You can find the geographical location of this water body by searching on water body ID in the interactive maps at www.sepa.org.uk/water/river_basin_planning.aspx



SEPA Contact Details: rbmp@sepa.org.uk
 © 2009 Scottish Environment Protection Agency

